

## SNK1010

## TAP HOLE REMOVAL

• Remove sink from packaging and support under the edges.



• Check the indicator to make sure you have selected correct handed hole.







Using a centre punch, chisel or sturdy instrument carefully hit the sink on the marker • indicated; this must be from the top glazed surface.










• When the tool has made a small hole, carefully chip away until the hole is the correct size.








When hole is finished the tap when fitted will cover any small irregularities. •







**Stephen Harrington** 

**Appliance Technical** 

12.11.10

